
(i) Crazy Iron



KTM Duke 390 2021-ID: 9009112/9009117/900911

Complete set and assembly scheme:


Left side:





Right side:



Place for mounting of plate:







Comments:

NEVER LOOSEN ENGINE BOLTS FROM THE LEFT AND RIGHT SIDES AT THE SAME TIME!!!

- 1. Contact a specialized service, do not install the cage yourself!
- 2. Remove fairing elements if they can interfere the installation of Plate
- 3. Remove original bolt from points A on the right side and attach Plate to points A with bolts and spacers and fix.
- 4. Remove original bolt from points A on the left side and attach Plate to points A with bolts and spacers and fix.
- 5. Install fairing back.
- 6. Remove original bolts from point 4 on the right side of motorcycle.
- 7. Attach right side of cage to points 4 and 2 and fix with bolt M10x120 through spacer 20x10x16 in point 4 and with bolt Bolt M10x40 in point 2
- 8. Remove original bolts from point 3 on the right side of motorcycle.
- 9. Attach right side of cage to points 3 and 1 and fix with bolt M10x120 through spacer 20x10x16 in point 3 and with bolt Bolt M10x40 in point 1
- 10. Install between points №5 and №6 the brace and fix it with Bolts M10x1,25x30. Choose the type of brace so that there is no contact when the motorcycle is moving.
- 11. Tighten the fasteners according to the table.
- 12. Install sliders in points NoNo1,2,7,8 and fix them with screws. In case Damper Cages use Damper sliders. In case crash bars install sliders only in points 1 and 2.

Tightening torques Nm						
Thread	Connection type					
	Steel	Aluminum				
M6	10	6				
M8	24	20				
M10	48	35				
M12	56	45				

Component table with according numbers in the photo:

	Component table with according numbers in the photo:									
№	Plate	Bolt M8x50 or Bolt M8x45	Items Spring washer	Spacer 20x10x17	Slider	Screw				
	Time	Dok Mondo of Bolt Mondo	G Washer	Spacer ZOATOAT	Shuci					
		Bolt M8x50 or Bolt M8x45	Spring washer	Spacer 20x10x17		Comming				
1			0							
		Bolt M10x40								
		(
	Plate	Bolt M8x50 or Bolt M8x45	Spring washer	Spacer 20x10x17	Slider	Screw				
		P.I.Mo.50 P.I.Mo.45	0							
	•	Bolt M8x50 or Bolt M8x45	Spring washer	Spacer 20x10x17		Chimin				
2			G							
		B	olt M10x40							
	Bolt M10x120	Spacer 20x10x16	Spring washer	Washer						
3			0	0						
	Bolt M10x120	Spacer 20x10x16	Spring washer	Washer						
4			0	0						
	Bolt M10x1,25x30	Spring washer	Washer	Brace Type 1 or L=300						
5		0	0							
	Bolt M10x1,25x30	Spring washer	Washer							
6		O	0							
7	Slider	Screw								
		Ommo								
	Slider	Screw								
8		Ommo								